

FIELD OF CALIBRATION : Pressure Measurement

INSTRUMENTS CALIBRATED	LABORATORY LOCATION		SITE CALIBRATION	
	RANGE	UNCERTAINTY	RANGE	UNCERTAINTY
PRESSURE MEASURING DEVICES				
	(-)0.9bar - 0.0bar	0.007 bar	(-)0.9bar - 0.0bar	0.007 bar
	0.0bar - 10 bar	0.005 bar	0.0bar - 10 bar	0.005 bar
	10bar - 20bar	0.013 bar	10bar - 20bar	0.013 bar
	20bar - 135bar	0.07 bar	20bar - 135bar	0.07 bar
	135bar - 300bar	1 bar	135bar - 300bar	1 bar
	300bar - 700bar	2 bar	300bar - 700bar	2 bar
DIFFERENTIAL PRESSURE MEASURING DEVICES				
	0Pa - 100Pa	2Pa	0Pa - 100Pa	2Pa
	100Pa - 500Pa	3Pa	100Pa - 500Pa	3Pa
	500Pa - 1000Pa	7Pa	500Pa - 1000Pa	7Pa
	1000Pa - 5000Pa	15Pa	1000Pa - 3000Pa	15Pa
	5000Pa - 7000Pa	30Pa	3000Pa - 5000Pa	20Pa
			5000Pa - 6000Pa	30Pa
			6000Pa - 7000Pa	35Pa